

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**GA894**  
**NNW**  
**> 1**  
**1.195 mi.**  
**6311 ft.**

**ROADWAY SPILL**  
**86TH ST/STILLWELL AVE**  
**BROOKLYN, NY**

**NY Spills** **S112807953**  
**N/A**

**Site 1 of 2 in cluster GA**

**Relative:**  
**Higher**

**Actual:**  
**11 ft.**

**SPILLS:**

Name: ROADWAY SPILL  
Address: 86TH ST/STILLWELL AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1212810 / 2012-11-30  
Facility ID: 1212810  
Facility Type: ER  
DER Facility ID: 431285  
Site ID: 475966  
DEC Region: 2  
Spill Cause: Human Error  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2012-11-29  
Investigator: SFRAHMAN  
Referred To: Not reported  
Reported to Dept: 2012-11-29  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial Vehicle  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2012-11-29  
Spill Record Last Update: 2012-11-30  
Spiller Name: STASHIA HALEEM  
Spiller Company: NYC TRANSIT  
Spiller Address: 86TH ST/STILLWELL AVE  
Spiller Company: 999  
Contact Name: STASHIA HALEEM  
DEC Memo: "Spoke with NYCT,646-252-5951 (Rochelle).Spill was cleaned up by NYCT crews. No soil was impacted. Case closed.(sr)"  
Remarks: "Apx 30 gallons spilled due to driver error, (unknown what at this time per caller). Estimated at 20 gallons to storm drain. Cleanup done by NYC transit. DUPLICATE TO SPILL 1212809"

**All Materials:**

Site ID: 475966  
Operable Unit ID: 1225807  
Operable Unit: 01  
Material ID: 2223129  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 30.00  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported